Plasmaterials, Inc. 2268 Research Drive Livermore, CA 94550

Ph: (925) 447-4030 Fx: (925) 447-4031 http://plasmaterials.com

MATERIAL SAFETY DATA SHEET

Section 1- Pi	RODUCT IDENTI	FICATI	ON				
COMPOSITION			PRODUCT NAME				
Sn			Tin				
	AZARDOUS INGI normal conditions do not r		_	ingestion or cont	act health	hazard.	
MATERIAL OR COMPONENT			Т%	EXPOSURE LIMITS			
				OSHA PEL (M		ACGIH TLV(MG/M3	
Tin	7440-31-5			2mg/cubi me	c eter	2mg/cubic meter	
Section 3- Pl	HYSICAL DATA						
MATERIAL IS (AT NO		APPERANCE AND ODOR Silvery Metal					
MELTING POINT (BAS		SPECIFIC GRAVITY					
23		5.75g/cc					
Section 4- FI	RE AND EXPLOS	SION					
Flash Point (Method Used) N/A		Flamma N/A	Flammable Limits N/A		LEL	UEL	
EXTINGUISHING MED	DIA						
SPECIAL FIRE FIGHTI	ing procedures	aratus if	f product	t is involved	in a fir	e.	
LINUSUAL FIRE AND E	EXPLOSION HAZARDS		_				
ONOSCAL LINE AND I	IN EGGION HAZARDS						
	EACTIVITY DATA	4					
STABILITY Stable			INCOMPATABILITY (MATERIALS TO AVOID) Strong acids, oxidizers halogens.				
CONDITIONS TO AVO	DID		Strong	acias, oxia	izers na	aiogens.	
None	,,,,						
HAZARDOUS DECOMI	POISTION PRODUCTS						
Will not occur							

Section 6- HEALTH HAZARD GUIDE

MAJOR EXPOSURE HAZARD

□Inhalation □Skin □Skin Absorption □Eye Contact □Ingestion

FFFECTS OF OVEREXPOSURE

INHALATION: Inhalation of dust and fumes must be avoided.

SKIN CONTACT: Not a route of entry into the body.

EYE CONTACT: Dust or fumes will be irritant.

INGESTION: Ingestion of dust or fumes must be avoided. Tin is not regarded as toxic but

excessive exposure can cause fever, nausea, stomach cramps or diarrhea.

EMERGENCY & FIRST AID PROCEDURES

INHALATION: Remove to fresh air. Get medical attention.

SKIN CONTACT: Wash thoroughly with soap and water. Remove contaminated clothing.

EYE CONTACT: Flush with water for 15 minutes. **INGESTION**: Get medical attention immediately.

Section 7- SPILL OR LEAK PROCEDURES

SPILL OR LEAK PROCUDRES

Allow to solidify and collect in sealed drums for disposal.

WASTE DISPOSAL METHODS

Return to supplied for reprocessing

Section 8- SPECIAL PROTECTION

RESPIRATORY

Only required if TLV's are exceeded. Use a NIOSH/OSHA approved respirator for dust and/or fumes.

VENTILATION

If fume or dust is being generated, mechanical ventilation must be provided to maintain exposure levels below TLV's.

EYE PROTECTION & PROTECTIVE CLOTHING

Wear safety glasses during soldering operations.

Section 9- SPECIAL PRECAUTIONS

Storage: Store in dry conditions.

The information in this MSDS was obtained from sources, which we believe are reliable. However, the information is provided without any representation or warranty, express or implied, regarding the accuracy or correctness.

The conditions or methods of handling, storage, use and disposal of the product are beyond our control and may be beyond our knowledge. For this and other reasons, we do not assume responsibility and expressly disclaim liability for loss, damage or expense arising out of or in any way connected with the handling, storage, use or disposal of the product.